Without PT, direct connection to power supply, packaging type power transducer with applied CT



Model PTD series


(Features)


- ●Power supply direct connect PT is unnecessary.
- Genuine accessary of small type clamp type AC current sensor
- Output of 0 ~ 5V as true active power measurement (power supply isolation type)
- ●Possible set CT sensitivity by 1A step between 1 ~ 100A with setting of surface DPS (dip switch)


(Example) PTD-1 E=100V


By I=50A (DPS10A+40A In case to earn e=2.5VDC P=100x50x $(2.5 \nearrow 5)$

Corresponding to P=2.5kW









[Specification] Ta=25°C				
Model	PTD-1	PTD-2	PTD-3	
Power supply circuit system and voltage	1Ø 100V / 200V-2 wires type (50/60Hz)	1Ø 100V / 200V-3 wires type (50/60Hz)	3Ø 200V-3 wires type (50/60Hz)	
CT sensitivity adjustment	On the front panel surface, 1A ~ 4A, 10A ~ 40A, set as the sum of current ON in 8 bits dip switch DPS, but not beyond 100A			
Rating power calculation method	5V at P=E • I (W)	5V at P=2 • E • I (W)	5V at P=√3 • E • I (W)	
Output voltage	0 ~ 5VDC/0 ~ rating power			
Maximum measuring range	0 ~ 10VDC / 0 ~ 200% of rating power (but, not beyond continuous rating current of CT)			
Accessory current sensor	Small size clamp type AC current sensor (CTT-16-CLS)			
Response time	0→100% output stable time :0.5 s			
Ripple voltage	Ripple voltage :100mVp-p (typ)			
Overall accuracy	±2%FS (50 ∕ 60Hz sine wave current power factor 1)			
Auxiliary power supply output	\pm 15V \angle \pm 10% Rating current less than 50mA (Possible to use as for external system)			
Withstand voltage	AC2000V(50/60Hz), 1min (Power supply terminal in a lump-output terminal in a lump)			
Insulation resistance	DC500V, \geq 100M Ω (power supply terminal in a lump-output terminal in a lump)			
Operating temperature	-20°C ~ +50°C , ≦85%RH, no condensation			
Screw torque	M4: 0.7N · m、M3: 0.3N · m			
Mass	Body approximately 230g, Accessory CT approximately 77g for each			
	0010			